


Setting sheet for FILLCONTROL Module: Control P



Button	Application
	Adds a new element
	Opens a Settingmenu
	Shows details
	Hides details
/	Element is activated/deactivated
/	Stop/Start Measurement

Button	Application
	Pausing Measurement
	Screenshot
/	Monitoring off/on
/	Shrinkage control off/on
/	Shear rate control off/on
/	Shear stress control off/on
/	Compression control off/on

Creating, Modifying, Monitoring and Controlling of Viscosity Measurement, Compression and Shrinkage/Save part Quality

